

SUIT SEAL

FIXES RIPS & HOLES FAST!

DIRECTIONS: Clean off mud and dirt with soap and water. Degrease the surface with alcohol. Apply Suit Seal directly to the area; spread an extra 5mm around the damaged area. Keep flat and allow to cure. Suit Seal is touch dry in 3-4 hours. Allow 10-12 hours for full cure.

SEAMS: Brush a thin layer of Suit Seal over the seam area. No waterproof tape is required. When cured, dust with talcum powder to get a non-stick surface.

RIPS & TEARS: Cover the front of the damaged area with sticky tape. Apply Suit Seal on reverse side, over the tape and overlap the edge of the hole by 5mm. Remove the sticky tape when cured.

WHEN FINISHED: Clean screw thread. Squeeze contents to the top of the tube and replace the cap, leaving no air under the cap. Roll up the tube. Adhesive is moisture sensitive. Store partially used tubes in the freezer. Warm up to room temperature before using again. See repair demonstrations on our website or YouTube channel.

WARNING: High flammable, harmful if inhaled. Keep away from all sources of fire or ignition. Do not smoke when using Suit Seal. Avoid all contact with eyes. If Suit Seal comes into contact with skin wash thoroughly with water immediately.

Net Wt. 21g.

Buy more at www.ndiver.com

NORTHERN DIVER INTERNATIONAL LTD.
EAST QUARRY, APPLBY LANE NORTH, APPLBY BRIDGE, WIGAN, WN6 9AE.
TEL +44 (0) 1257 25 44 44 | EMAIL - INFO@NDIVER.COM

